

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

HAER
MD
I-MLOTH,
IC-

Consolidation Coal Company Mine No. 11, Air/Manway Shaft
East side of State Route 936
Midlothian vicinity
Allegany County
Maryland

HAER No. MD-87-C

Photographer: John P. Herr

April 1993

- MD-87-C-1 AIR/MANWAY SHAFT WALL AND FAN HOUSE FOUNDATION WALL FROM
NORTHWEST. AEROVANE FAN AT UPPER LEFT, SCAFFOLD AND LEPLEY
VENTILATOR AT UPPER RIGHT.
- MD-87-C-2 MANWAY SHAFT DOORS FROM NORTH. METAL FRAGMENT AT REAR.

Key to Photographs
CONSOLIDATION COAL COMPANY MINE No. 11, Air/Manway Shaft
HAER No. MD-87-C (page 2)

